

Service Bulletin

Bulletin No.: 20-NA-078


Date: November, 2020

TECHNICAL

Subject: Malfunction Indicator Lamp (MIL) Illuminated - DTC P0741 Set

Brand:	Model:	Model Year:		VIN:		Engine	Tuonomiosion
		from	to	from	to	Engine:	Transmission:
Chevrolet	Express	2019	2020			MYC, MY	MYC, MYD
	Silverado LD		2019				
	Silverado 1500 (New Model)						
	Silverado 1500	2020	- 2020				
	Silverado 2500/3500						
	Suburban	2019					
	Tahoe						
GMC	Savana	2019	2020				
	Sierra Limited		2019				
	Sierra 1500 (New Model)						
	Sierra 1500	2020	2020				
	Sierra 2500/3500						
	Yukon	2019					

Involved Region or Country	North America	
	Some customers may comment that the MIL is Illuminated.	
Condition	Some customers may also comment that the torque converter doesn't seem to lock up.	
	Some technicians may find DTC P0741 (Torque Converter Clutch (TCC) System Stuck Off) set as an active or history code.	



Service Procedure

Refer to 4-5-6 Clutch Overhaul in SI.

Parts Information

Causal Part	Description	Part Number	Qty
Х	HOUSING, 4-5- 6 CLU	24237556	
N/A	COVER KIT, A/ TRNS FLUID PUMP	24248573	1
N/A	SEAL, T/CV FLUID (24237531	
N/A	Fluid, Transmission (DEXRON®VI)	88865601 (U.S.) 19420142 (Canada)	6-12.4 qts (5.7-11.7 liters)
N/A	FILTER KIT, A/ TRNS FLUID	Refer to EPC	1

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
8466430	4-5-6 Clutch Plate Replacement	Use the Published Labor Operations Time

Bulletin No.: 20-NA-078 November, 2020 Page 3

Version	2
Modified	Released March 31, 2020 Revised November 23, 2020 - Added the Silverado and Sierra 2500/3500 HD, 2020 Model Year and Fluid Filter to Parts Information section.